

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

707601835

FIELD INSPECTION FORMLoc ID 305730 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281389	WELL	PA	07/21/2020	GW	123-23405	THOR B 32-19	PA

General Comment:

This is a PLUGGED & ABANDONED WELL inspection.

Well(s): 1: Plugged & Abandoned | PA.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs

(336634, 302380).

(Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery formerly served 2 Location IDs

(305730, 327645).

(Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID

(447717).

(Battery: Inactive | Shut-down).

Reference:A.) Field Inspection Report doc. #707601829 and/or Location ID #336634
for TA Well(s) info. (2).B.) Field Inspection Report doc. #707601831 and/or Location ID #302380
for TA Well(s) info. (1).C.) Field Inspection Report doc. #707601833 and/or Location ID #336634
for PA Well(s) info. (1).D.) Field Inspection Report doc. #707601835 and/or Location ID #305730
for PA Well(s) info. (1).E.) Field Inspection Report doc. #707601837 and/or Location ID #327645
for PA Well(s) info. (1).F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717
for Battery / Facility, Equipment info.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA. Equipment removed.](#)

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 281389 Type: WELL API Number: 123-23405 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 09/13/2023 at approximately 14:48 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: THOR B-65N64W/32SENW Location ID: 305730 Well Name(s): Thor B 32-19. API: 123-23405. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>Centralized Battery formerly served 2 Location IDs (305730, 327645). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive Shut-down).</p> <p>Reference: A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2). B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1). C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1). D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1). E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1). F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6S on file. Plugging, cut/cap date: 07/21/2020. Approved. Plugged & Abandoned PA well GPS coordinates: 40.359070 / -104.578150</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/13/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707601836	Site photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6250184