

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope 43-17

Loc ID: 424559

Inspection: 709100060



Exhibit A

CA: Illegible wellhead signs, sign at tank battery is not installed properly, and emergency contact number on tanks illegible from a distance. Install signs to comply with Rule 605.a.

CA Resolution: Operator has properly re-installed sign at tank battery. Additional matters regarding signage, including installing legible emergency contact number(s) on tanks, are currently being addressed to comply with Rule 605.a.



Exhibit A



Exhibit B



Exhibit C




Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H

CA: Undesirable plant species located throughout the site. Comply with rule 606.c.

CA Resolution: Field has appropriately addressed the identified tumbleweeds and debris on location and have properly cleared/cleaned the area to comply with Rule 606.c.