

## Inspection Photos


Location Name: CAERUS PICEANCE LLC, GASAWAY FED-66S99W/26NWSW

Location ID: 323867

Date: 9/13/2023



Entrance to Location – Photo #06382



Wellhead – Photo #06384



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, GASAWAY FED-66S99W/26NWSW

Location ID: 323867

Date: 9/13/2023



Separator – Photo #06383



Tank Battery – Photo #06385