

Inspection Photos

Location Name: TEP Rocky Mountain LLC PA 33-32 Pad

Location # 335103



Sep 13, 2023 at 11:54:41 AM
CO

Photo # 9085 From entrance to location



Sep 13, 2023 at 11:54:45 AM
CO

Photo # 9086 From entrance to location

Inspection Photos

Location Name: TEP Rocky Mountain LLC PA 33-32 Pad

Location # 335103



Photo # 9087 Location



Photo # 9088 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC PA 33-32 Pad

Location # 335103



Photo # 9109 Location



Photo # 9095 Open ended pipe/wildlife hazard