

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: LUHMAN-62N67W 4SESE

Loc ID: 331118

Inspection: 702402295



Exhibit A



Exhibit B

CA: Undesirable vegetation growing tall along access road and around WH. Comply with Rule 606.

CA Resolution: Operator reports that weeds and overgrowth have been addressed and cleared from around the wellhead and along the access road to comply with Rule 606.