

Operator: EXTRACTION OIL & GAS INC
Location Name: BECKY-62N69W 36SESW
Loc ID: 321341
Inspection: 702402342



Exhibit A

CA: Sign doesn't reflect current operator name. Comply with Rule 605.

CA Resolution: Operator has updated and installed a new label to reflect the current Operator and to comply with Rule 605.



Exhibit A

CA: Undesirable vegetation growing along access road and location ROW. Comply with Rule 606.

CA Resolution: Operator reports that weeds and debris were mitigated with mowing and line trimming to comply with Rule 606.c.