


**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**




**Unused equipment**



**Which phone number?**

North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052



Crude oil or process water



Staining



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Open to wildlife**



**Open end tank valves**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**




**Open end tank valves**



**Open end tank valves**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Open heat trace valve**



**Venting**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Open to wildlife**



**Debris. Damaged anchor**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Overgrown vegetation**



**Brush. Open to wildlife**

**North Shore Exploration and Production LLC**  
**Smith 1**  
**Location ID: 313052**



**Poorly displayed**



**Debris**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Debris**



**Staining**



North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052



**Trash. Staining**



**No spill containment**



North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052



Debris



Debris



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Original ECD burned out**



**Replacement ECD not hooked up**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Open to wildlife**



**Unused equipment**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Debris**



**Open to wildlife**



**North Shore Exploration and Production LLC**  
**Smith 1**  
**Location ID: 313052**



**Staining**



**Staining**



North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052




Debris



Debris



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**




**Debris inside containment**



**Debris**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Compressor base full of oil**



**Staining around compressor**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Staining North of compressor**



**Venting**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Location view from Southwest corner**



**Location view from Northwest corner**



**North Shore Exploration and Production LLC  
Smith 1  
Location ID: 313052**



**Location view from Southeast corner**



**Location view from Northeast corner**