

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403525892

Date Received:

09/11/2023

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

8 of 8 CAs from the FIR responded to on this Form

8 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10524

Name of Operator: GRMR OIL & GAS LLC

Address: P.O. BOX 6280

City: BROOMFIELD State: CO Zip: 80021

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Chad Collins

Phone

7207371398

Email

collins.chad@grmroilandgas.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 702501695

Inspection Date: 08/02/2023

FIR Submit Date: 08/04/2023

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: GRMR OIL & GAS LLC

Company Number: 10524

Address: P.O. BOX 6280

City: BROOMFIELD State: CO Zip: 80021

### LOCATION - Location ID: 441283

Location Name: Myers Number: 19-11HA County: MOFFAT

Qtrqr: NESW Sec: 19 Twp: 5N Range: 90W Meridian: 6

Latitude: 40.368317 Longitude: -107.541414

### FACILITY - API Number: 05-081- -00 Facility ID: 441282

Facility Name: Myers Number: 19-11HA

Qtrqr: NESW Sec: 19 Twp: 5N Range: 90W Meridian: 6

Latitude: 40.368317 Longitude: -107.541414

### CORRECTIVE ACTIONS:

1 ☒ CA# 177303

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 08/18/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator  
Comment:

All contaminated soil was removed and replaced with clean dirt. ~1 5 gallon bucket of dirt was removed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 177304

Corrective Action: Remove and properly dispose of oily waste and impacted soil.

Date: 08/18/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: All contaminated soil was removed and replaced with clean dirt. ~1 5 gallon bucket of dirt was removed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 177305

Corrective Action: The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.

Date: 08/13/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: Gas calibration data was placed in a laminated sheet directly above the gas meter in clear line of sight.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

4 ☒ CA# 177306

Corrective Action: Remove unused equipment and supplies

Date: 08/09/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: All unused equipment and supplies were removed

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

5 ☒ CA# 177307

Corrective Action: Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.

Date: 08/09/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: Another round of herbicide was applied to the location

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

6 ☒ CA# 177308

Corrective Action: The Wellhead sign will identify: The Well name; The API Number; and Its legal location, including the quarter/quarter section.

Date: 10/02/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: Wellhead sign now identifies what is required

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**7** ☒ CA# 177309

Corrective Action: The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Tank battery site; Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well (s); and Location, including the quarter/quarter section, of the Tank battery.

Date: 09/02/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: Tank battery sign has all required information on it

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**8** ☒ CA# 177310

Corrective Action: Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container.

Date: 08/13/2023

Response: CA COMPLETED

Date of Completion: 08/17/2023

Operator Comment: All containers have new placards that are clear and visible

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All issues have been resolved in a timely manner

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chad Collins

Signed: \_\_\_\_\_

Title: Geologist

Date: 9/11/2023 12:43:24 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403525892	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files