

Interim Reclamation and Stormwater Inspection

September 13, 2023

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 460656

Inspection Document #: 697504857

Weld County, CO

NWNE Section 28 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ROY SWD FACILITY
Location ID: 460656



Photo 1. Google Earth aerial imagery from 5/16/2023 illustrating the location. Operator has failed to perform interim reclamation around the well location (red polygon).



Inspection Photos
Location Name: ROY SWD FACILITY
Location ID: 460656



Photo 2. Photo taken from the entrance of location, facing South. Photo illustrates the Operator sign.



Photo 3. Photo taken from the well location entrance, facing Southeast. Photo illustrates sheds over each wellheads.

Inspection Photos
Location Name: ROY SWD FACILITY
Location ID: 460656



Photo 4. Photo taken from the northwestern location, facing East. Photo illustrates Operator has failed to perform interim reclamation.



Photo 5. Photo taken from the northwestern location, facing South. See comments under Photo 4.

Inspection Photos
Location Name: ROY SWD FACILITY
Location ID: 460656



Photo 6. Photo taken from the topsoil stockpile, facing East. Photo illustrates annual, weedy vegetation (tumbleweeds and cheatgrass) established on the stockpile.

