

Inspection Photos

Loc: 307772

Operator: OXY USA INC

Inspection Date: 9/13/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. There is erosion occurring along the road that needs to be repaired.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307772 | Date: 9/13/2023

Inspection Photos



Photo 2. Facing northwest toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307772 | Date: 9/13/2023

Inspection Photos



Photo 3. Facing north toward the wellsite.

