

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, JOLLEY-68S96W/4SESE

Location ID: 334079

Date: 9/14/2023



Entrance to Location – Photo #06393



South End of Location – Photo #06394

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, JOLLEY-68S96W/4SESE

Location ID: 334079

Date: 9/14/2023



Wellhead – Photo #06395



Separators – Photo #06397

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, JOLLEY-68S96W/4SESE

Location ID: 334079

Date: 9/14/2023



Tank Battery – Photo #06396