

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. DUTTON-68S96W/12NWNE

Location ID: 334159

Date: 9/14/2023



Entrance to Location – Photo #06419



North End of Location – Photo #06420

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. DUTTON-68S96W/12NWNE

Location ID: 334159

Date: 9/14/2023



Wellheads – Photo #06421



Separators – Photo #06422

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, N. DUTTON-68S96W/12NWNE

Location ID: 334159

Date: 9/14/2023



Tank Battery – Photo #06423

