

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope 11-20

Loc ID: 424418

Inspection: 709100062



Exhibit A



Exhibit B

CA: Illegible wellhead signs, sign at tank battery is not installed properly, and emergency contact number on tanks illegible from a distance. Install signs to comply with Rule 605.a.

CA Resolution: Operator has properly re-installed sign at tank battery. New signs for multiple areas of the location have been ordered to ensure that information displayed is up to date and legible. Additional matters regarding signage, including installing legible emergency contact number(s) on tanks, are currently being addressed to comply with Rule 605.a.



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J

CA: Trash and debris onsite. Comply with Rule 606.d.

CA Resolution: Field has appropriately cleared identified trash and debris from location to comply with Rule 606.d.

CA: Undesirable plant species located throughout the site. Comply with rule 606.c.

CA Resolution: Field has appropriately addressed the identified tumbleweeds and debris on location and properly cleared/cleaned the area to comply with Rule 606.c.

CA: Unused equipment on site. Comply with Rule 606.

CA Resolution: Unused equipment/material has been identified and removed from the location to comply with Rule 606.