

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location ID: 324099



Photo # 9365 From entrance to location



Photo # 9368 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location ID: 324099




Photo # 9369 Location



Photo # 9371 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 21-7 Pad

Location ID: 324099



Photo # 9385 Tank capacity incorrect



Photo # 9386 Correct tank capacity