

Inspection Photos
Hilcorp Wilson 34-9 29-4
API 067-08081



Photo #1. View of corrective action identified in FIR Doc.#712700639.



Photo 2. View of completed corrective action.

Inspection Photos
Hilcorp Wilson 34-9 29-4
API 067-08081



**Photo #3. View of corrective action identified in FIR
Doc.#712700639.**

Photo #4. View of completed corrective action.