

Inspection Photos
Hilcorp Wilson 34-9 29-4
Api 067-08876



**Photo #1. View of corrective action identified in FIR
Doc.#712700638.**



Photo #2. View of removed tank, resolved corrective action.

Inspection Photos
Hilcorp Wilson 34-9 29-4
Api 067-08876



Photo #3. View of corrective action identified in FIR
Doc.#712700638.



Photo #4. View of removed tank, resolved corrective action.