

Final Reclamation Inspection

September 13, 2023

Operator: LUNDVALL OIL & GAS INC - 51760

Well API#: 123-13003

Inspection Document #: 697504865

Weld County, CO

SWNE Section 18 T5N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: LUNDVALL #18
Well API#: 123-13003



Photo 1. Photo taken from the eastern associated tank battery location, facing South. Photo illustrates the Operator has removed all equipment from the tank battery.



Photo 2. Photo taken from the western associated tank battery location, facing West. See comments under Photo 2.



Inspection Photos
Location Name: LUNDVALL #18
Well API#: 123-13003



Photo 3. Photo taken from the well location, facing West. Photo illustrates the crop growth is reflective of reference crop areas.

