

**Operator: Extraction Oil and Gas**

**Location Name: Winder 9-41**

**Loc ID: 430438**

**Inspection: 697007750**



**Exhibit A**

**CA:** 400 bbls maintenance tanks lack contents, capacity and NFPA placards Rule 605.h. Install sign to comply with Rule 605.h.

**CA Resolution:** Labels regarding the contents and capacity have been installed on the maintenance tanks on the Winder pad to comply with rule 605.h.