

State of Colorado
Energy & Carbon Management Commission



Document Number:
403534601

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:
09/19/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Labowskie, Steve

steve.labowskie@state.co.us

. General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 712700606

Inspection Date: 08/30/2023

FIR Submit Date: 08/30/2023

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325804

Location Name: LEROY MCCAWE GAS UNIT B- M34N8W Number: 21SWNE County: LA PLATA

Qtrqr: SWNE Sec: 21 Twp: 34N Range: 8W Meridian: M

Latitude: 37.179794 Longitude: -107.719070

FACILITY - API Number: 05-067-00 Facility ID: 215404

Facility Name: LEROY MCCAWE B Number: 1

Qtrqr: SWNE Sec: 21 Twp: 34N Range: 8W Meridian: M

Latitude: 37.179794 Longitude: -107.719070

CORRECTIVE ACTIONS:

1 CA# 180207

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 09/30/2023

Response: CA COMPLETED

Date of Completion: 12/13/2022

Operator Comment: Meter tube inspection and calibration is valid (last calibration completed on 12/13/2022) and not overdue. IKAV has discussed with ECMC Compliance Supervisor regarding inspections received.

COGCC Decision: _____

COGCC
Representative:

3 CA# 180209

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 09/12/2023

Response: CA COMPLETED

Date of Completion: 09/18/2023

Operator
Comment: Cleaned up stained soil from around muffler.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Partial CA completed for stained soil and confirmation of calibration. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 9/19/2023 11:15:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403534640	Leroy McCaw B1, CA photos stains
-----------	----------------------------------

Total Attach: 1 Files