

# Inspection Photos

Loc: 308913

Operator: OGRIS OPERATING LLC

Inspection Date: 9/18/2023

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the access road.



## Inspection Photos



**Photo 2.** Facing northwest toward the location.



## Inspection Photos



**Photo 3.** Facing northwest at the fill slope. There are noxious weeds in this area that need to be controlled. Red arrow → Canada thistle



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:308913 | Date: 9/18/2023

## Inspection Photos



**Photo 4.** There is erosion along the fill slope that needs to be repaired and stabilized.

