


Inspection Photos

Operator: HUNTINGTON ENERGY LLC – 42300

Location Name: FOSSIL FEDERAL #6-18

Location ID: 316856 API #: 05-113-06199

Inspection Date: 9/5/2023 - 9/18/2023 Inspection Doc#: 693806454



Rig on location



Lift nipple welded on 5 1/2" csg.

Inspection Photos

Operator: HUNTINGTON ENERGY LLC – 42300

Location Name: FOSSIL FEDERAL #6-18

Location ID: 316856 API #: 05-113-06199

Inspection Date: 9/5/2023 - 9/18/2023 Inspection Doc#: 693806454



Wellhead and csg cut and removal



Information plate with weep hole welded on to CSG.