

ATTACHMENT B



SITE NAME: J. Nelson 33-23 Wellhead							DATE: 7/13/2023	REM. PROJECT #: 29462	WEATHER: 90S SUNNY		
SITE DIRECTIONS: SOUTH OF COUNTY ROAD 52							CLIENT: PDC				
LEGALS AND LAT/LONG: 40.359250, -104.893280							TASMAN PERSONNEL: RY				
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: North				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
7/13/2023 09:02	FLR02 @ 5'	1.4	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
7/13/2023 09:18	FL01-02 @ 5'	0.1	No Staining	No Odor	Yes	Lab	Separator				
7/13/2023 09:25	FL01-01 @ 5'	0.9	No Staining	No Odor	Yes	Lab	Emission Control Device (ECD)				
7/13/2023 10:53	WH01 @ 6'	0.7	No Staining	No Odor	Yes	Lab	Dump Line				
7/13/2023 10:57	FLR01 @ 4'	0.5	No Staining	No Odor	Yes	Lab	Wellhead		1		
7/13/2023 11:07	BKG01 @ 4'	0.4	No Staining	No Odor	Yes	On-Hold	Flowline		1		
7/13/2023 11:11	BKG01 @ 6'	0.6	No Staining	No Odor	Yes	On-Hold	Other:				
7/13/2023 14:38	WHS01-N @ 0-6"	0.0	No Staining	No Odor	Yes	Grab	Soil Loads Removed				
7/13/2023 14:40	WHS01-E @ 0-6"	0.1	No Staining	No Odor	Yes	Grab	IMPACTED SOIL IDENTIFIED?				
7/13/2023 14:42	WHS01-S @ 0-6"	0.1	No Staining	No Odor	Yes	Grab	ESTIMATED VOLUME OF IMPACTS:				
7/13/2023 14:44	WHS01-W @ 0-6"	0.0	No Staining	No Odor	Yes	Grab	Date		Number		CY
							Total Removed		0 0		
							Disposal Facility:				
							Groundwater Recovery				
							DATE GW ENCOUNTERED:			DEPTH:	
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				


Photographic Log



Equipment ID: FLR02 @ 5'		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID: FL01-02 @ 5'		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log



Equipment ID: FL01-01 @ 5'		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID: WH01 @ 6'		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log



Equipment ID: FLR01 @ 4'		Equipment Type:		Equipment ID: WHS01-N @ 0-6"		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log



Equipment ID: WHS01-E @ 0-6"			Equipment Type:			Equipment ID: WHS01-S @ 0-6"			Equipment Type:		
Material:		Volume:	Contents:			Material:		Volume:	Contents:		
Notes/Conditions:						Notes/Conditions:					

Photographic Log



Equipment ID: WHS01-W @ 0-6"		Equipment Type:		Equipment ID: BKG01		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			