

Inspection Photos

Location Name: Elmer Kaufman-62N63W 18SWSE Tank Battery

Location ID: 317706



Removed Overgrown Vegetation



Removed Overgrown Vegetation


Inspection Photos

Location Name: Elmer Kaufman-62N63W 18SWSE Tank Battery

Location ID: 317706



Not updated to current operator sign, still shows old operator



Missing Capacity Label and weathered NFPA placard