

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403532887

Date Received:

09/19/2023

Spill report taken by:

Anderson, Laurel

Spill/Release Point ID:

484825

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC	Operator No: 10633	<b>Phone Numbers</b> Phone: (720) 3158934 Mobile: ( ) Email: lkelly@civiresources.com
Address: 1801 CALIFORNIA STREET #2500		
City: DENVER	State: CO Zip: 80202	
Contact Person: Luke Kelly		

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403467622

Initial Report Date: 07/18/2023 Date of Discovery: 07/17/2023 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR SWNE SEC 19 TWP 2N RNG 68W MERIDIAN 6

Latitude: 40.126691 Longitude: -105.045103

Municipality (if within municipal boundaries): County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

#### Reference Location:

Facility Type: TANK BATTERY

☒ Facility/Location ID No 451044

Spill/Release Point Name: Regnier Farms 19H-B268

☐ Well API No. (Only if the reference facility is well) 05- -

☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Has the subject Spill/Release been controlled at the time of reporting? Yes

#### Land Use:

Current Land Use: CROP LAND

Other(Specify):

Weather Condition: Clear

Surface Owner: FEE

Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A compromised produced water dump line at the Regnier Farms 1J-19H separator resulted in 0.27 bbls of fluid to be spilled to the surface and a currently unknown volume to the subsurface. The impacted soil will be removed following utility locates and hauled for disposal. Confirmation soil samples will be collected in compliance with COGCC Table 915-1. Additionally, a waste characterization sample from the source area will be collected and submitted for analysis of COGCC Table 915-1 constituents.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
7/17/2023	COGCC EPS	Laurel Anderson	-on file	Notified of Release
7/17/2023	Weld Co. OEM	Dave Burns	-on file	Notified of Release
7/17/2023	Surface Owner	on file	-on file	Notified of Release

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_
- Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_
- Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_
- No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_
- Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_
- Was there damage during excavation? \_\_\_\_\_
- Was CO 811 notified prior to excavation? \_\_\_\_\_
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 07/18/2023		
----	--------------------------------------	--	--

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO    Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply)    ☒ Soil    ☐ Groundwater    ☐ Surface Water    ☐ Dry Drainage Feature

Surface Area Impacted:    Length of Impact (feet): \_\_\_\_\_    Width of Impact (feet): \_\_\_\_\_

Depth of Impact (feet BGS): \_\_\_\_\_    Depth of Impact (inches BGS): \_\_\_\_\_

How was extent determined?

The extent of the impact was determined through visual delineation and confirmed through confirmation soil sampling.

Soil/Geology Description:

Nunn Clay Loam, 0 to 1 percent slopes. CL - silty clay

Depth to Groundwater (feet BGS)	25	Number Water Wells within 1/2 mile radius:	0
---------------------------------	----	--	---

If less than 1 mile, distance in feet to nearest	Water Well	3310	None <input type="checkbox"/>	Surface Water	2531	None <input type="checkbox"/>
	Wetlands	2576	None <input type="checkbox"/>	Springs		None <input checked="" type="checkbox"/>
	Livestock	1423	None <input type="checkbox"/>	Occupied Building	1127	None <input type="checkbox"/>

Additional Spill Details Not Provided Above:

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 09/18/2023

Root Cause of Spill/Release Pipe, Weld, or Joint Failure

Other (specify) \_\_\_\_\_

Type of Equipment at Point of Spill/Release: Dump Line

If "Other" selected above, specify or describe here:

\_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

A compromised transition piece from poly to steel on the produced water line at the Regnier Farms 1J-19H separator resulted in 0.27 bbls of fluid to be spilled to the surface and a currently unknown volume to the subsurface.

Describe measures taken to prevent the problem(s) from reoccurring:

Crestone has implemented an upgraded chemical program to proactively reduce the number of corrosion related releases.

Volume of Soil Excavated (cubic yards): 32

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal ☐ Onsite Treatment

☐ Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): \_\_\_\_\_

Volume of Impacted Surface Water Removed (bbls): \_\_\_\_\_

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

- Basis for Closure: ☒ Corrective Actions Completed (documentation attached, check all that apply)
- ☒ Horizontal and Vertical extents of impacts have been delineated.
- ☒ Documentation of compliance with Table 915-1 is attached.
- ☒ All E&P Waste has been properly treated or disposed.
- ☐ Work proceeding under an approved Form 27 (Rule 912.c).
- Form 27 Remediation Project No: \_\_\_\_\_
- ☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

Crestone over-excavated all remaining impacts and resampled on 9/6/2023. Based on the attached release assessment report from the most recent confirmation soil sampling activities, all samples are in compliance with ECMC Table 915-1 regulatory limits.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Costin McQueen

Title: Senior Env Specialist Date: 09/19/2023 Email: cmcqueen@civiresources.com

<u>COA Type</u>	<u>Description</u>
	<p>Based on the information presented, it appears that no further action is necessary at this time and the ECMC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding ECMC standards or if groundwater is found to be impacted, then further investigation and/or remediation activities may be required. In addition, the surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules.</p> <p>For locations with active ongoing oil and gas operations, comply with Rule 1003 interim reclamation requirements.</p>
1 COA	

### **Attachment List**

<u>Att Doc Num</u>	<u>Name</u>
403532887	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403534181	ANALYTICAL RESULTS
403534862	FORM 19 SUBMITTED

Total Attach: 3 Files

### **General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)