

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad

Location ID: 335392



Photo # 9705 From entrance to location



Photo # 9695 From entrance to location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad

Location ID: 335392



Photo # 9696 Location



Photo # 9706 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad

Location ID: 335392



Photo # 9707 Location



Photo # 9708 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 332-33 Pad

Location ID: 335392




Photo # 9720 Open ended pipe/wildlife hazard



Photo # 9721 Open ended pipe/wildlife hazard