

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2023

Submitted Date:

09/19/2023

Document Number:

701007344

FIELD INSPECTION FORMLoc ID 324814 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10634

Name of Operator: P O & G OPERATING LLC

Address: 5847 SAN FELIPE SUITE 3200

City: HOUSTON State: TX Zip: 77057

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Nash, Charlotte	(713) 589-8186	charlotte_nash@pogresource s.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212860	WELL	SI	10/01/2020	OW	061-06220	TALLMAN 23-2	PA

General Comment:

P&A Inspection

Location**Lease Road:**

Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 212860 Type: WELL API Number: 061-06220 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: HP Oilfield Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 2015/1590/1200/750Cement Volume (sx): 380 SXSGood Return During Job: YESCement Type: Class AComment:

HALDE WATER, CODELL WELL SERVICE, HP OILFIELD SERVICE. MIRU HP, PUMP 60 SXS THRU CICR @ 2015' W/10 SXS ON TOP. MIRU CODELL, POOH W/TBG RIH W/CICR TO 1590'. MIRU HP, PUMP 50 SXS THRU W/10SXS ON TOP. MIRU CODELL, POOH W/TBG, RIH W/CICR TO 1200'. MIRU HP, 80SXS THRU W/10SXS ON TOP. MIRU CODELL, POOH W/TBG, RIH W/CICR TO 750'. MIRU HP, PUMP 50 SXS THRU W/10SXS ON TOP. MIRU CODELL, POOH W/TBG. MIRU HP, PUMP 100 SXS W/CMT TO SFC.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT