

Inspection Photos

9/19/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117

Inspection No: 696205247

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 1: Photos 1-2 taken from the northwestern edge of the working pad surface. Photos provide an overview of the production areas from northeast, east, south to southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 3: Photos example showing the interim areas of the Location vegetation predominantly desirable plant species, with Basin Wildrye and Wheatgrass species being the most apparent.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 4: Tank battery facility on the north end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 5: Photo taken from the north end of the Location. Photo shows unused and unmarked container stored adjacent to the separator equipment.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 6: Photo taken from the access road north of the Location. Photo shows unused fence equipment stored along road.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 7: Photo shows two unmarked anchors on the southern working pad surface.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 8: Photo shows unmarked anchor on the western working pad surface.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335117



Photo 9: Photo shows unmarked anchor on the eastern working pad surface.