

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/11NWNE

Location ID: 334982

Date: 9/19/2023



Entrance to Location – Photo #06452



Wellheads – Photo #06454

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/11NWNE

Location ID: 334982

Date: 9/19/2023



Separators – Photo #06456



Tank Battery – Photo #06453

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/11NWNE

Location ID: 334982

Date: 9/19/2023



Unsecured Separator Hatch – Photo #06457

