

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 9775 From entrance to location



Photo # 9776 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901

Sep 19, 2023 at 10:03:08 AM



Photo # 9779 Location

Sep 19, 2023 at 10:03:45 AM



Photo # 9780 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 9781 Location



Photo # 9782 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 9783 Location



Photo # 9791 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 9799 Open ended load line



Photo # 9800 Weeds/undesirable plant species

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 9801 Weeds/undesirable plant species



Photo # 9802 Weeds/undesirable plant species

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SAVAGE RMV 15-35 Pad

Location ID: 323901



Photo # 9805 Weeds/undesirable plant species



Photo # 9808 Weeds/undesirable plant species