

Work Completion Report

Contractor: Peerless

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
BROWN/CANNON TANK BATTERY	N/A	Armando Munoz	9/08/2023

Work Summary	Reclamation Type	Land Use
Removed weed carcasses from equipment on site and windrow. Mowed weeds down with brush cutter	Stormwater	Other

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Facility Weed Control	Normal	No	Location(s): BROWN 21-35 Notes: Removed weed carcasses from equipment on site and windrow.

COMPLETION DETAILS

Total Area Affected: **0.10 acres**
 Seed Mix: **None used**
 Crop Type:
 Soil Type: **Clay Loam**
 Stabilization Date: **9/08/2023**
 Seeding Date:
 Mulch: **None**
 Straw Bales: **NA**
 Soil Amendment Type: **None**
 Soil Amendment Rate: **NA**
 Imported Top Soil: **NA**
 Top Soil Source: **NA**
 General Notes:

LOCATION INFO

Location(s) – Name: BROWN 21-35

COGCC ID: **310114**

Well APIs at Location: **12325925**

Land Rep:

Land Owner: **Cannon Land Co**

Rec Contractor PO(s): **M&E -**

Vendor PO(s):

Billing Notes: **DJ-L0385**

Legal Address: **(WELD) NWNE 35 3N66W**

Topsoil Source:

Variance Notes:

Private Utility Notes:

Wildlife Restrictions:

General Notes:

COGCC Doc #'s:

Initial Reclaim Complete Date:

Maint. Reclaim Complete Date:

PHOTOS

Photo Name: Site Map

Description:




Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: Brown 2

Description:



Photo Name: Brown 3

Description:

