

Inspection Photos

Location Name: DF Ranch 10-11, 13, 42 & 44 Tank Battery

Location ID: 460765



Photo 1 – Tank Battery




Photo 2 – Capacity Label faded no longer visible



Inspection Photos

Location Name: DF Ranch 10-11, 13, 42 & 44 Tank Battery

Location ID: 460765



Photo 3 – Tank Battery Sign



Photo 4 – Heater Treaters and ECD



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources