

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Access road to location



Entrance to location

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Unmarked anchor



Wellhead sign missing API Number

Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868



Sep 19, 2023 at 10:59:47 AM

Debris



Sep 19, 2023 at 11:00:13 AM

Wellhead, weeds

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Unmarked anchor



Erosion, soil migration

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Erosion, soil migration



Unmarked anchor

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**




Debris, staining



Open to wildlife

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Debris, open to wildlife

Out of compliance

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Debris



Trash

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Production facility



Bermed pit

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Oily waste, staining



Staining

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Weeds

Weeds

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Staining



Debris

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Sep 19, 2023 at 11:18:03 AM

Unlabeled tank, no containment



Sep 19, 2023 at 11:18:24 AM

Debris

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Debris



Compressor

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Location view from Southeast corner



Location view from Northeast corner

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Location view from Northwest corner



Location view from Southwest corner