

# Inspection Photos

9/19/2023

**Operator:** LARAMIE ENERGY LLC #10433

**Location ID:** 335595

**Inspection No:** 696205255

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335595



**Photo 1:** Photos taken from the tow of the fill slopes on the northeast and east end of the Location. Photo shows Operator has implemented hydromulch on the slopes. Control measure appeared to be in proper functioning condition at time of inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 335595



September 19, 2023



September 19, 2023

**Photo 3:** Photo left taken from the interim areas on the southwest end of the Location. Operator appears to have conducted additional reclamation work in conjunction with a hydromulch application. Photo right also shows erosion logs have been maintained.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: LARAMIE ENERGY  
Location ID: 33559



**Photo 4:** Photo left shows the outlet from the working pad surface has been maintained and sediment removed. Photo right shows the slope drain outlet lacks a properly engineered and armored outlet, resulting in off-site degradation.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources