

Inspection Photos

9/19/2023

Operator: LARAMIE ENERGY LLC #10433

Location ID: 383264

Inspection No: 696205257

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 383264



Photo 1: Photos taken from the north end of the Working Pad Surface. Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 383264



Photo 2: See comments under photo 1.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 383264



September 19, 2023

Photo 3: Wells on Location

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 383264



Photo 4: Photo shows containment berm at the cuttings stockpile has been maintained.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 383264



September 19, 2023

Photo 5: Stained soils remain apparent on the Working Pad Surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 383264



Photo 6: Photo taken from the northwest end of the Location, facing east. Photo shows drill cuttings have been returned to the stockpile, and additional containment measures implemented.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location ID: 383264



September 19, 2023

Photo 7: Additional work to protect the topsoil stockpiles on Location has been performed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources