

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 1 – Tank Battery

Photo 2 – NFPA Label faded no longer visible

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 3 – Tank Battery Sign

Photo 4 – Separators, VRU and ECD

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 5 – Wellhead – Chemical Tank missing label

Photo 6 – Wellhead – Chemical Tank missing label

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 7 – Separators and ECD

Photo 8 – Unused Chemical Stand

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 9 – Unused Stands, Chemical Drums, Loadline Bucket, Tarp, Metal Siding and Tumbleweeds

Photo 10 – Unused Netting and Solar Panel

Inspection Photos
Location Name: DF Ranch PC GK 02-77HN
Location ID: 428119



Photo 11 – Gas Meter Houses

Photo 12 – Backside of Tanks