

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR SHCT 1 Pad

Location ID: 323821




Photo # 21 From entrance to location



Photo # 22 From entrance to location

Location ID: 323821



Sep 20, 2023 at 12:15:13 PM

Photo # 24 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR SHCT 1 Pad

Location ID: 323821



Photo # 25 Location



Photo # 26 Hole in base of secondary containment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SUPERIOR SHCT 1 Pad

Location ID: 323821



Photo # 29 Debris