

Operator: EXTRACTION OIL & GAS INC
Location Name: DEVORE-63N66W/34NENE
Loc ID: 336458
Inspection: 709400371



Exhibit A



Exhibit B

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c.

CA Resolution: Operator has addressed identified weeds and location has been appropriately mowed and maintained to comply with Rule 606.c.