

Inspection Photos

Loc: 309185

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 9/20/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the recontoured location. There is an active lease road that goes through the top side of the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:309185 | Date: 9/20/2023

Inspection Photos



Photo 2. Facing north toward the location. Perennial vegetation appears to be fully established.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309185 | Date: 9/20/2023

Inspection Photos



Photo 3. North side of the location facing southwest toward the recontoured location.



Inspection Photos



Photo 4. West side of the location facing south toward the recontoured location.



Inspection Photos



Photo 5. Facing east at the upper portion of the location. There are wattles that remain which need to be removed..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309185 | Date: 9/20/2023

Inspection Photos



Photo 6. The stormwater wattles will need to be removed prior to final inspection.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:309185 | Date: 9/20/2023