

Inspection Photos

Loc: 333374

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 9/20/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the location.



Inspection Photos



Photo 2. Facing east toward the fill slope which is stabilized with vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:333374 | Date: 9/20/2023

Inspection Photos



Photo 3. There is vehicle rutting at the location which is not stabilized.



Inspection Photos



Photo 4. There are stained soils at the wellhead that need to be cleaned up.

