

Inspection Photos

Loc: 334130

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 9/20/2023

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the location.



Inspection Photos



Photo 2. Facing east toward the cut slope which is stabilized with vegetation.



Inspection Photos



Photo 3. Facing northeast toward the fill slope which is stabilized with vegetation.

