

# Final Reclamation Inspection

August 29th, 2023

Operator: 44 Canyon LLC - 195

Location ID: 385787

Inspection Document #: 714000003

La Plata County, CO

Township: SESE 34 34.5N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 1.** Overview photo of the center of the well disturbance taken from entrance.





Inspection Photos  
Location Name: Federal 34/2-34-1  
Location ID: 385787



**Photo 2.** View of the northern project area back slope that has sparse vegetation and rill erosion. Stabilization required in this area.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

API #: 06707514





8/29/23  
+37.246858,-107.836595  
180° S

**Photo 3.** View of rilling erosion in the middle of the disturbance. Stabilization issues remain apparent.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

API #: 06707514



# Inspection Photos

Location Name: Federal 34/2-34-1

Location ID: 385787



**Photo 4.** Down and upslope views of erosional channel deepening in southwest corner of disturbance. Currently BMPS are not sufficient for this area.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

API #: 06707514



Inspection Photos  
Location Name: Federal 34/2-34-1  
Location ID: 385787



**Photo 5.** View of reference area comprised of Pine, Juniper, Gambel oak, Antelope bitterbrush and Indian ricegrass.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

API #: 06707514