

Final Reclamation Inspection

August 29th, 2023

Operator: Chevron Mid Continent LP - 16695

Location ID: 307024

Inspection Document #: 714000004

La Plata County, CO

Township: NWNW 2 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Crader 3-3
Location ID: 307024



Photo 1. View of the center of the disturbance taken from the entrance.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-09614



Photo 2. View of the fill slope on the eastern edge of the disturbance. Vegetation appears consistent with adjacent reference area.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #:067-09614

Inspection Photos
Location Name: Crader 3-3
Location ID: 307024



Photo 3. View of cut slope on northern edge of disturbance. Cut slope remains unstabilized with little to no vegetation establishment.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #:067-09614



Photo 4. View of reference area comprised of gambel oak, antelope bitterbrush, indian rice grass and pepperweed.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #:067-09614