

Final Reclamation Inspection

September 1st, 2023

Operator: BP American Production Co - 10000

Location ID: 385638

Inspection Document #: 714000006

La Plata County, CO

Township: NESE 27 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lobato 1-27
Location ID: 385638



Photo 1. View of the eastern edge of the disturbance.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-06534

Inspection Photos
Location Name: Lobato 1-27
Location ID: 385638



Photo 2. View of the western edge of the disturbance. Vegetation appears more sparse on the western edge compared to eastern edge of disturbance.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-06534

Inspection Photos
Location Name: Lobato 1-27
Location ID: 385638



Photo 3. Photo from the southwestern corner shows interim has well established vegetation comprised mostly of smooth brome and western wheatgrass.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-06534

Inspection Photos
Location Name: Lobato 1-27
Location ID: 385638



Photo 4. Reference area comprised of gambel oak, pine and smooth brome.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06534