

Final Reclamation Inspection

September 1st, 2023

Operator: BP American Production Co - 10000

Location ID: 385639

Inspection Document #: 714000007

La Plata County, CO

Township: SENW 26 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lobato 1-26
Location ID: 385639



Photo 1. Overview of the disturbance. Access road remains to access the active well located to the south.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06535

Inspection Photos
Location Name: Lobato 1-26
Location ID: 385639



Photo 2. Overview of the western edge of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06535

Inspection Photos
Location Name: Lobato 1-26
Location ID: 385639



Photo 3. Overview of the eastern edge of the disturbance. Both sides of the disturbance are progressing towards the 80% vegetation threshold standards.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-06535

Inspection Photos
Location Name: Lobato 1-26
Location ID: 385639



Photo 4. Musk thistle and field bindweed observed flowering on location and need to removed.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-06535

Inspection Photos
Location Name: Lobato 1-26
Location ID: 385639



Photo 5. Overview of the northwestern edge of the disturbance. Numerous wooden stakes and wattle BMP's that need to be removed.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-06535

Inspection Photos
Location Name: Lobato 1-26
Location ID: 385639



Photo 6. Reference area comprised of gambel oak, pine, squirrel tail and indian rice grass.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

API #: 067-06535