

Final Reclamation Inspection

September 1st, 2023

Operator: BP American Production Co - 10000

Location ID: 325529

Inspection Document #: 714000009

La Plata County, CO

Township: NESE 31 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 1. Overview of the disturbance.

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 2. Overview of interim on southern edge of disturbance that shows well established perennial vegetation.

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 3. Bare area mentioned in previous inspection has been mulched.

Inspection Photos
Location Name: Gearhart 1-31
Location ID: 325529



Photo 4. Reference area comprised of oak, pine, smooth brome and squirrel tail.

