

# Interim and Stormwater Inspection

September 4th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325694

Inspection Document #: 714000014

La Plata County, CO

Township: SWSW 20 34N 9W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Arthur Mason A#1  
Location ID: 325694



**Photo 1.** Overview of the disturbance taken from the entrance.

Inspection Photos  
Location Name: Arthur Mason A#1  
Location ID: 325694



**Photo 2.** Western side of the disturbance taken from the southern edge.

Inspection Photos  
Location Name: Arthur Mason A#1  
Location ID: 325694



**Photo 3.** Southern edge of the disturbance taken from the western edge.

Inspection Photos  
Location Name: Arthur Mason A#1  
Location ID: 325694



**Photo 4.** Eastern edge of the disturbance taken from the entrance. Pile of gravel needs to be removed.