

Interim and Stormwater Inspection

September 4th, 2023

Operator: Simcoe LLC - 10749

Location ID: 325777

Inspection Document #: 714000016

La Plata County, CO

Township: NWNW 27 34N 9W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Simon Land & Cattle #27-01, 1
Location ID: 325777



Photo 1. Overview of the disturbance taken from the entrance facing center.



Inspection Photos
Location Name: Simon Land & Cattle #27-01, 1
Location ID: 325777



Photo 2. Eastern edge of disturbance taken from the southern edge.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06972

Inspection Photos
Location Name: Simon Land & Cattle #27-01, 1
Location ID: 325777



9/4/23
+37.167718,-107.819914
297° NW

Photo 3. Northern edge of the disturbance taken from the eastern edge.

Inspection Photos
Location Name: Simon Land & Cattle #27-01, 1
Location ID: 325777



Photo 4. Western edge of the disturbance taken from the northern edge.



Inspection Photos

Location Name: Simon Land & Cattle #27-01, 1

Location ID: 325777



Photo 5. Weeds and debris on location that need to be treated/removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06972