

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2023

Submitted Date:

09/22/2023

Document Number:

701007365

FIELD INSPECTION FORMLoc ID 337527 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286617	WELL	PR	06/01/2015	GW	125-10308	SHIVELY 32-1	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Metal panels around meter shed and VGS		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried by meter shed		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	286617	Type:	WELL	API Number:	125-10308	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Location and access are grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT