

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2023

Submitted Date:

09/22/2023

Document Number:

701007372

FIELD INSPECTION FORM

Loc ID 303185 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	(970) 332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252617	WELL	PR	06/01/2015	GW	125-06493	B ALLEN 1-1	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
	Type	Access	
	comment:	Gravel road through pasture	
	Corrective Action:		Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Lease sign for associated wells mounted to meter shed	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Metal panels around wellhead, VGS and meter shed	
	Corrective Action:		Date:

Equipment:			corrective date
Type:	Ancillary equipment	# 1	
	Comment:	Telemetry equipment	
	Corrective Action:		Date:
Type:	Gas Meter Run	# 3	
	Comment:	Shared meter run for (Allen 1-1, 43-1 & Shively 42-1)	
	Corrective Action:		Date:
Type:	Vertical Separator	# 3	
	Comment:	3-Vertical gas separators 50% buried by meter shed	
	Corrective Action:		Date:

Venting:			
	Yes/No		
	Comment:		
	Corrective Action:		Date:

Flaring:			
Type			

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 252617 Type: WELL API Number: 125-06493 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Allen 1-1, 43-1 & Shively 42-1\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT