

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 9/21/2023



SE Corner of Location – Photo #06490



Northwest Corner of Location – Photo #06494

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 9/21/2023



Wellhead – Photo #06491



Separator – Photo #06492

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, OXY USA INC-67S96W/10NWNE

Location ID: 323862

Date: 9/21/2023



Tank Battery – Photo #06493